



WATER HEATER CONTROLS

Service Replacements Made Easy

Grow your service sales with Resideo's atmospheric and ultra low NOx gas water heater controls.



STATUS LIGHT CODE

Light Color	STATUS
Blue	Normal Operation
Red	System Problems
Yellow	High Temperature Shutdown
Green	Temperature Sensor Failure
Orange	Gas Valve Failure
Purple	Igniter Failure
White	Normal Operation
Black	System Problems

SCALDING RISK INCREASES WITH HOTTER WATER

TO LIGHT PILOT: PRESS & HOLD IN PILOT POSITION. PRESS CENTER BUTTON ONLY. RELEASE WHEN LIGHTS ARE ON.

PILOT OFF

LOW

HOT

FROM

STATUS LIGHT CODE

Light Color	STATUS
Blue	Normal Operation
Red	System Problems
Yellow	High Temperature Shutdown
Green	Temperature Sensor Failure
Orange	Gas Valve Failure
Purple	Igniter Failure
White	Normal Operation
Black	System Problems

SCALDING RISK INCREASES WITH HOTTER WATER

TO LIGHT PILOT: PRESS & HOLD IN PILOT POSITION. PRESS CENTER BUTTON ONLY. RELEASE WHEN LIGHTS ARE ON.

PILOT OFF

LOW

HOT

FROM

SCALDING RISK INCREASES WITH HOTTER WATER

TO LIGHT PILOT: PRESS & HOLD IN PILOT POSITION. PRESS CENTER BUTTON ONLY. RELEASE WHEN LIGHTS ARE ON.

PILOT OFF

LOW

HOT

FROM

WT88 Series Gas Water Heater Control

Stock less. Sell more. With Resideo Water Heater Controls, only eight models are needed to replace multiple A.O. Smith, Bradford White, and Rheem controls. Consolidate your inventory while expanding your sales opportunities and capturing more business.

With nationwide availability and the easy selection process, you'll save time and make more profits per job – all while delivering great value and quality for your customers.



Cross Reference

AFTERMARKET SKUS	RESIDEO OEM PART NUMBER	OEM PART NO	OEM PART NO REPLACEMENTS	OEM
WT8840A1000 1" insulation tank, 4" WC setting	WV8840A1000 WV8840A1001	222-47463-01A 222-47463-01E	415-52907-01	Bradford White
WT8840A1500 2" insulation tank, 4" WC setting	WV8840A1050 WV8840A1051	222-47463-02A 222-47463-02E	415-52907-02	Bradford White
WT8860A1000 2" insulation tank, 5" WC setting - ULN	WV8860A1009 WV8860A1010	222-48863-01	415-52915-01	Bradford White
WT8840B1000 1" insulation tank, 5" WC setting	WV8840B1042 WV8840B1109 WV8840B1110	316910-000 316910-000 321166-000	100112336 9007884005	A.O. Smith
WT8840B1500 2" insulation tank, 5" WC setting	WV8840B1059 WV8840B1117 WV8840B1118	316910-001 316910-001 321166-001	100112337 9007885005	A.O. Smith
WT8860B1000 2" insulation tank, 5" WC setting - ULN	WV8860B1309 WV8860B1310	100073010 318618-000	100093970 9007631005	A.O. Smith
WT8840C1000 1.5" insulation tank, 4" WC setting	WV8840C1406	AP16910E	SP20832E	Rheem
WT8840C1500 2" insulation tank, 4" WC setting	WV8840C1605	AP16910B	SP20832B	Rheem

Replacement Water Heater Controls for your customers.
More upsell opportunities for you – with less stock.

Service Benefits

SERVICE FOR ALL BRANDS

Models will service most water heaters manufactured in the last 10 years.

NATIONAL DISTRIBUTION

Convenient for contractors as controls are available at most leading distributors.

Product Highlights

STATUS LED

Trims repair time by up to 30 minutes.

RESETTABLE EMERGENCY TEMPERATURE CUTOFF

Reduces cost and labor time by eliminating valve replacement.

LARGER PILOT FLAME

Reduces customer callbacks.

ACCURATE TEMPERATURE SENSING

Improves comfort and eliminates scalding risk.

ANTI-SCALDING ALGORITHMS

Protects children and elderly from water exceeding the setpoint.



Resideo Technologies, Inc.

1985 Douglas Drive North
Golden Valley, MN 55422
1-800-468-1502
resideo.com

For more information

resideo.com/pro